

TURBULATORS

Proper Fluid Temperature

Fluid and reduce the flow and pressure across the system by passing through the system before being returned to the reservoir. The levels expected for the power steering system after a power steering system after a

TRAINING



MODULE

PLEWS &
EDELMANN

Electronic Power Steering



Tech Tip

See just how easy it is to both inspect and replace the drive belt inside an electric rack and pinion.



9601

Electric Rack and Pinion Drive Belt Replacement for 2010-2012 Ford Fusion, Lincoln MKZ, and Mercury Milan



Edelmann 9606



Edelmann 9608

In Partnership with:



TRAINING MODULE

In an effort to provide the best possible information to assist with the understanding of the competitive advantages of the Edelmann Elite® Power Steering Total Solution®, we are pleased to provide our training module packed with in-depth information regarding all of our products.

INFORMATIVE VIDEOS


Our entire [media library](#) is available for helpful visuals.

PRODUCT BULLETINS

Deep dives into some of our most specialized benefits.

FEATURE CALL-OUTS

Specific talking points for each part in our program.



TECH LINE:
855-333-5832



module.plews-edelmann.com